CONNECTORS M 12 POWER

Assembly Instructions

Straight Connector Female / Male Thread, S- / T-Coding

1.



2.



3.



4.





5.



6.





⚠ Shield is not allowed to touch second O-ring

7.



8.